



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor 

Minerals Regulatory Program

Date of Report: 04/16/2008

Mine Name: Levan Chicken Creek
Operator Name: Sunroc Corp. - Tony Christofferson

Permit number: M0230016

Inspection Date: 04/09/08

Time: 9:00 am

Inspector(s): Leslie Heppler
Other Participants: Rod Dolph
Mine Status: Active

Weather: Cold and Snowing


| Elements of Inspection | Evaluated | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Water Impoundments | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Air Quality | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection: This was a routine annual inspection

Inspection Summary: Blast warning signs (one at west and one at east end) of main access road had different dates. Localized highwall failure on east side of the pit. Small debris flow on main access road east of section 34 mine pit. Section 34 mine pit was actively hauling from stockpile placed at the base of the highwall, +5 end dumps in the que. Stockpile was not well sorted and trackhoe was used to size sort large boulders. Area southwest of Section 33 pit was reclaimed, but is/was outside of permit area. Section 33 mine pit was not inspected; a inspection is still needed for the Section 33 mine, when weather/road conditions permit. See attached photos.


Conclusions and Recommendations: Bond escalation was due on 01/21/07. Operator has 30 days to escalate bond.

Inspector's Signature

 Resubmit
06-30-11

Date:

Photos Taken 04-09-08



lah:pb

cc: Susan White, Lynn Kunzler, Jed Pearson
Sunroc - Tony Christofferson, Rod Dolph
Agency - Uinta NF- administered by Manti-LaSal NF
GPS map and Photos